

FITNESS CERTIFICATE

To be filled by the Inspecting Officer (Asst. Engineer)

(Re: G.O. Ms. 20/70/ PWD Dt. 23 - 01 -1970)

1. Name of the Officer PRIYA MARY PHILIP
2. Name of the School St. Alphonsa public school kudamala
3. Location with name of Education District/ Sub. District kottayam nwal
4. Classification of Building as specified in column 4 of the application for fitness certificate and size.
..... 35.50 X 10.75 X 3.20 Base floor 398 m²
..... 35.50 X 10.75 X 3.20 gf - 651 m²
..... 35 X 50 X 10.75 X 3.20 FF - 651 m²
..... S.F - 651 m²
5. Period for which the certificate is issued 2024-2025
6. Nature of defects , if any
a) Foundation and basement
b) Superstructure
c) Doors and Windows
d) Wood work wrought and put up
e) Roof
f) Flooring
g) Miscellaneous (Cracks, etc.)
..... Nil
7. Any major defects noticed which will render the building unsafe in any manner No
8. Whether maintenance works have been done properly Yes
9. Whether the structure is sound or not for conducting classes sound enough to conduct classes in Natural weather condition

Note : 1. The stability of the structure should be examined also with reference to location, altitude, intensity of wind, exposure of flood etc. 2. Any additional observations if deemed necessary for the certificate may be furnished separately with this certificate.

CERTIFICATE

certified that the school building was inspected by me on 28-05-2024 and found to be fit / unfit to conduct classes, for the period 2024-2025 for the reasons stated above.

Place : Aymanam
Date : 28-05-2024



Priya Philip
PRIYA MARY PHILIP
ASSISTANT ENGINEER
LID & EW SECTION
AYMANAM GRAMA PANCHAYAT
PEN : 692669